

Avaya

7004 Exam

Avaya Communication Server 1000 for Avaya Aura®
Maintenance Exam

Thank you for Downloading 7004 exam PDF Demo


You can Buy Latest 7004 Full Version Download

https://www.certkillers.net/Exam/7004

https://www.certkillers.net

Question: 1

Click the Exhibit button.



A customer has asked if the Communication Server 1000 RIs. 7 x system can route anyone that dial an unassigned number in the customer's DID range to the Attendant. In reviewing the current configuration as shown in the exhibit, what do you conclude? (Choose two)

- A. only internal station users are routing to the Attendant
- B. internal station users and non tie line users are routing to the Attendant
- C. all caller types are receiving an overflow tone
- D. NET_DATA Attendant and tie trunk users are receiving an overflow tone

Answer: B

Question: 2

A customer has deployed a Communication Server 1000 RIs. 7 x system at their site. Their sales department is expanding and you have been asked to add Ave new telephones with the same capabilities as the existing telephones in the department. Which programming command should you use to complete this task?

- A. Move to DN
- B. Move from TN
- C. Copy from DN
- D. Copy from TN

Answer: D

Oue	stion:	. 2	
Ouc	SLIUII.		

For a situation where you use the CDP feature at a switch equipped with the MARS software package, which statement are correct? (Choose two)

- A. Use steering codes tor CDP calls that are the same as the assigned NARS Access Cades.
- B. Use steering codes tor CDP calls that are distinct from those assigned NARS Access Cades.
- C. You can integrate CDP numbers with the NARS Uniform Dialing Plan (UDP).
- D. You cannot share Route Lists, Digit Manipulation tables and Time-of-Day schedule with NARS.

Answer: B, C

Question: 4


A customer has a Communication Server 1000 RIs. 7 x system at their site. You have been asked to add the Call Pickup feature to the ten IP telephones in the sales department. The customer wants to be sure active calls are not lost when the change are made. Which Phones Configuration feature can be enabled allowed you to ensure changes to the telephones are not transmitted to the call server until the telephone is not busy?

- A. Bulk change
- B. Courtesy change
- C. Group change
- D. Template change

Answer: B

Question: 5

Click the Exhibit button.




Given the customer Route List index shown in the exhibit, what is the first expensive route that a call placed on that RLI could take?

- A. Entry 0
- B. Entry 1
- C. Entry 2
- D. Entry 3

Question: 6

Click the Exhibit button.



Given the customer's programmed database shown in the exhibit and AC 1 = 9, over which RLI will a call placed to 9-1-912-534-2222 complete?

- A. RLI 9
- B. RLI 4
- C. RLI 3
- D. RLI 2
- E. call will not complete as dialed

Answer: B

Thank You for trying 7004 PDF Demo

To Buy Latest 7004 Full Version Download visit link below

https://www.certkillers.net/Exam/7004

Start Your 7004 Preparation

[Limited Time Offer] Use Coupon "CKNET" for Further discount on your purchase. Test your 7004 preparation with actual exam questions.